

Fiterman Hall
Airtek Project #05-0867

No	Time	Dur	COMPONENT	COLOR	SIDE	SUBSTRATE	SPACE	FL #	ROOM	Results	DI	PbC	PbC Error
1	10/28/2005 8:23	56.66	SHUTTER_CAL									8.18	0
2	10/28/2005 8:25	21.33	Calibrate							Positive	1.04	1	0.1
3	10/28/2005 8:26	21.34	Calibrate							Positive	2.69	1.1	0.1
4	10/28/2005 9:14	3.13	Wall	BEIGE	Side 2	SHEETROCK	Staircase	1	Staircase A	Negative	1.58	0	0.02
5	10/28/2005 9:15	2.5	Wall	BEIGE	Side 3	PLASTER	Staircase	1	Staircase A	Negative	1	0	0.02
6	10/28/2005 9:16	4.38	Wall	BEIGE	Side 3	CINDER BLK	Staircase	1	Staircase A	Negative	2.31	0.09	0.06
7	10/28/2005 9:17	1.88	Stair Riser	BEIGE	Room Center	METAL	Staircase	1	Staircase A	Negative	1.32	0.06	0.07
8	10/28/2005 9:18	4.38	Stair Under	BEIGE	Room Center	METAL	Staircase	1	Staircase A	Negative	1.77	0.1	0.05
9	10/28/2005 9:18	1.25	Baluster	BEIGE	Room Center	METAL	Staircase	1	Staircase A	Negative	2.23	0.15	0.18
10	10/28/2005 9:18	1.89	Hand Rail	BEIGE	Room Center	METAL	Staircase	1	Staircase A	Negative	1	0	0.02
11	10/28/2005 9:22	4.39	Wall	BEIGE	Side 1	CINDER BLK	Staircase	2	Staircase A	Negative	1.9	0.03	0.03
12	10/28/2005 9:22	3.13	Wall	BEIGE	Side 2	CINDER BLK	Staircase	2	Staircase A	Negative	2.69	0.04	0.07
13	10/28/2005 9:23	4.38	Wall	BEIGE	Side 2	PLASTER	Staircase	2	Staircase A	Negative	1.89	0.03	0.03
14	10/28/2005 9:24	3.13	Wall	BEIGE	Side 3	CINDER BLK	Staircase	2	Staircase A	Negative	4.86	0.16	0.2
15	10/28/2005 9:26	1.88	EC	BEIGE	Side 1	METAL	Staircase	2	Staircase A	Negative	1	0	0.02
16	10/28/2005 9:27	4.38	FLOOR	BEIGE	ROOM CENTER	CONCRETE	Staircase	2	Staircase A	Negative	3.08	0.13	0.07
17	10/28/2005 9:29	5.65	Stair Tread	BEIGE	ROOM CENTER	METAL	Staircase	2	Staircase A	Negative	3.09	0.17	0.07
18	10/28/2005 9:29	1.88	Stair Riser	BEIGE	ROOM CENTER	METAL	Staircase	2	Staircase A	Negative	1.95	0.14	0.13
19	10/28/2005 9:30	1.88	Stair Strin	BEIGE	ROOM CENTER	METAL	Staircase	2	Staircase A	Negative	1.49	0.3	0.18
20	10/28/2005 9:31	1.88	Hand Rail	BEIGE	ROOM CENTER	METAL	Staircase	2	Staircase A	Negative	4.47	0.27	0.3
21	10/28/2005 9:32	1.88	Newel Post	BEIGE	ROOM CENTER	METAL	Staircase	2	Staircase A	Negative	1.99	0.4	0.2
22	10/28/2005 9:32	15.67	Baluster	BEIGE	ROOM CENTER	METAL	Staircase	2	Staircase A	Null	3.23	1	0.1
23	10/28/2005 9:33	17.55	Baluster	BEIGE	ROOM CENTER	METAL	Staircase	2	Staircase A	Null	3.14	1	0.1
24	10/28/2005 9:33	6.29	Baluster	BEIGE	ROOM CENTER	METAL	Staircase	2	Staircase A	Negative	3.05	0.8	0.2
25	10/28/2005 9:34	3.76	Stair Under	BEIGE	ROOM CENTER	METAL	Staircase	2	Staircase A	Negative	4.42	0.05	0.06
26	10/28/2005 9:37	1.88	StaircaseDb	LT-BLUE	Side 1	METAL	Staircase	5	Staircase A	Negative	1	0	0.02
27	10/28/2005 9:38	1.89	StaircaseDr	LT-BLUE	Side 1	METAL	Staircase	5	Staircase A	Negative	1	0	0.02
28	10/28/2005 9:39	3.13	WALL	BEIGE	Side 1	CINDERBLOCK	Staircase	5	Staircase A	Negative	4.43	0.11	0.15
29	10/28/2005 9:39	2.51	WALL	BEIGE	Side 2	CINDERBLOCK	Staircase	5	Staircase A	Negative	1	0	0.02
30	10/28/2005 9:39	4.38	WALL	BEIGE	Side 3	CINDERBLOCK	Staircase	5	Staircase A	Negative	6.65	0.26	0.17
31	10/28/2005 9:41	8.76	Ceiling	BEIGE	Ceiling	CONCRETE	Staircase	5	Staircase A	Negative	10	0.3	0.63
32	10/28/2005 9:42	4.38	FLOOR	BEIGE	FLOOR	CONCRETE	Staircase	5	Staircase A	Negative	1.76	0.1	0.05
33	10/28/2005 9:44	4.38	Stair Tread	BEIGE	ROOM CENTER	METAL	Staircase	5	Staircase A	Negative	2.01	0.14	0.06
34	10/28/2005 9:45	1.89	Stair Riser	BEIGE	ROOM CENTER	METAL	Staircase	5	Staircase A	Negative	2.83	0.13	0.15
35	10/28/2005 9:45	1.89	Stair Strin	BEIGE	ROOM CENTER	METAL	Staircase	5	Staircase A	Negative	2.42	0.04	0.08
36	10/28/2005 9:46	5.01	Hand Rail	BEIGE	ROOM CENTER	METAL	Staircase	5	Staircase A	Negative	1	0	0.02
37	10/28/2005 9:46	1.88	Baluster	BEIGE	ROOM CENTER	METAL	Staircase	5	Staircase A	Negative	2.72	0.08	0.12
38	10/28/2005 9:47	2.5	Newel Post	BEIGE	ROOM CENTER	METAL	Staircase	5	Staircase A	Negative	1.12	0.02	0.03
39	10/28/2005 9:48	1.88	Stair Under	BEIGE	ROOM CENTER	METAL	Staircase	5	Staircase A	Negative	3.44	0.16	0.2
40	10/28/2005 9:51	1.88	Staircase Db	ORANGE	Side 1	METAL	Staircase	8	Staircase A	Negative	1	0	0.02
41	10/28/2005 9:52	1.89	Staircase Dr	ORANGE	Side 1	METAL	Staircase	8	Staircase A	Negative	1	0	0.02
42	10/28/2005 9:53	4.38	WALL	BEIGE	Side 1	CINDERBLOCK	Staircase	8	Staircase A	Negative	4.7	0.06	0.07
43	10/28/2005 9:54	5.02	WALL	BEIGE	Side 2	CINDERBLOCK	Staircase	8	Staircase A	Negative	1	0	0.02

Fiterman Hall
Airtek Project #05-0867

No	Time	Dur	COMPONENT	COLOR	SIDE	SUBSTRATE	SPACE	FL #	ROOM	Results	DI	PbC	PbC Error
44	10/28/2005 9:54	4.41	WALL	BEIGE	Side 3	CINDERBLOCK	Staircase	8	Staircase A	Negative	1.46	0.03	0.02
45	10/28/2005 9:55	16.3	Ceiling	BEIGE	Ceiling	CONCRETE	Staircase	8	Staircase A	Negative	3.2	0.6	0.4
46	10/28/2005 9:56	4.39	Floor	BEIGE	Floor	CONCRETE	Staircase	8	Staircase A	Negative	2.35	0.1	0.06
47	10/28/2005 9:57	1.88	Stair Riser	BEIGE	Room Center	METAL	Staircase	8	Staircase A	Negative	2.25	0.09	0.12
48	10/28/2005 9:58	4.39	Stair Tread	BEIGE	Room Center	METAL	Staircase	8	Staircase A	Negative	2.43	0.15	0.07
49	10/28/2005 9:58	1.88	Stair Strin	BEIGE	Room Center	METAL	Staircase	8	Staircase A	Negative	1	0	0.02
50	10/28/2005 9:59	2.5	Hand Rail	BEIGE	Room Center	METAL	Staircase	8	Staircase A	Negative	2.88	0.05	0.09
51	10/28/2005 9:59	2.5	Newel Post	BEIGE	Room Center	METAL	Staircase	8	Staircase A	Negative	2.07	0.02	0.04
52	10/28/2005 10:00	1.88	Baluster	BEIGE	Room Center	METAL	Staircase	8	Staircase A	Negative	1.51	0.06	0.07
53	10/28/2005 10:00	1.88	Stair Under	BEIGE	Room Center	METAL	Staircase	8	Staircase A	Negative	7.42	0.05	0.18
54	10/28/2005 10:01	1.88	Standpipe	RED	Side 3	METAL	Staircase	8	Staircase A	Negative	1	0.01	0.02
55	10/28/2005 10:02	1.88	Standpipe	RED	Side 3	METAL	Staircase	8	Staircase A	Negative	1	0	0.02
56	10/28/2005 10:02	1.88	Standpipe	RED	Side 3	METAL	Staircase	8	Staircase A	Negative	1	0	0.02
57	10/28/2005 10:07	5.01	POST	LT-YELLOW	Room Center	METAL	Loading Dock	8	LOAD. DOCK	Positive	1.27	1.3	0.1
58	10/28/2005 10:08	2.5	Column Cover	LT-YELLOW	Room Center	METAL	Loading Dock	8	LOAD. DOCK	Negative	1.06	0.4	0.2
59	10/28/2005 10:16	21.32	Calibrate							Positive	1.1	1.2	0.1
60	10/28/2005 10:17	20.71	Calibrate							Positive	2.76	1.2	0.1
61	10/28/2005 10:46	56.64	SHUTTER_CAL									7.28	0
62	10/28/2005 10:48	22.57	Calibrate							Positive	1.07	1.1	0.1
63	10/28/2005 10:49	21.38	Calibrate							Positive	2.79	1.2	0.1
64	10/28/2005 11:51	4.41	Stair Tread	BEIGE	Room Center	METAL	Staircase	11	Staircase A	Negative	3.15	0.28	0.11
65	10/28/2005 11:52	1.89	Stair Riser	BEIGE	Room Center	METAL	Staircase	11	Staircase A	Negative	2.2	0.09	0.11
66	10/28/2005 11:52	1.89	Stair Strin	BEIGE	Room Center	METAL	Staircase	11	Staircase A	Negative	1.34	0.01	0.03
67	10/28/2005 11:53	1.88	Baluster	BEIGE	Room Center	METAL	Staircase	11	Staircase A	Negative	1.8	0.08	0.09
68	10/28/2005 11:54	2.5	Newel Post	BEIGE	Room Center	METAL	Staircase	11	Staircase A	Negative	3.26	0.06	0.1
69	10/28/2005 11:55	1.88	Stair Under	BEIGE	Room Center	METAL	Staircase	11	Staircase A	Negative	5.51	0.23	0.31
70	10/28/2005 11:59	2.5	Hand Rail	BEIGE	Room Center	METAL	Staircase	11	Staircase A	Negative	2.52	0.04	0.07
71	10/28/2005 12:01	4.39	WALL	BEIGE	WALL 1	CINDERBLOCK	Staircase	11	Staircase A	Negative	2.42	0.06	0.04
72	10/28/2005 12:02	5.03	WALL	BEIGE	WALL 2	CINDERBLOCK	Staircase	11	Staircase A	Negative	1.65	0.05	0.03
73	10/28/2005 12:02	4.38	WALL	BEIGE	WALL 3	CINDERBLOCK	Staircase	11	Staircase A	Negative	2.86	0.09	0.06
74	10/28/2005 12:06	5.01	LANDING	BEIGE	ROOM CENTER	CONCRETE	Staircase	11	Staircase A	Negative	2.21	0.14	0.06
75	10/28/2005 12:09	4.38	Stair Tread	BEIGE	ROOM CENTER	METAL	Staircase	15	Staircase A	Negative	2.17	0.15	0.06
76	10/28/2005 12:10	1.88	Stair Riser	BEIGE	ROOM CENTER	METAL	Staircase	15	Staircase A	Negative	2.15	0.1	0.12
77	10/28/2005 12:10	1.88	Stair Strin	BEIGE	ROOM CENTER	METAL	Staircase	15	Staircase A	Negative	1.16	0.01	0.02
78	10/28/2005 12:10	0.63	Baluster	BEIGE	ROOM CENTER	METAL	Staircase	15	Staircase A	Null	2.1	0.04	0.17
79	10/28/2005 12:10	1.88	Baluster	BEIGE	ROOM CENTER	METAL	Staircase	15	Staircase A	Negative	1.62	0.06	0.08
80	10/28/2005 12:11	1.88	Newel Post	BEIGE	ROOM CENTER	METAL	Staircase	15	Staircase A	Negative	2.96	0.04	0.09
81	10/28/2005 12:11	1.88	Hand Rail	BEIGE	ROOM CENTER	METAL	Staircase	15	Staircase A	Negative	2.64	0.03	0.07
82	10/28/2005 12:12	1.88	Stair Under	BEIGE	ROOM CENTER	METAL	Staircase	15	Staircase A	Negative	1.49	0.01	0.04
83	10/28/2005 12:13	4.4	WALL	BEIGE	Wall 1	CINDERBLOCK	Staircase	15	Staircase A	Negative	2.12	0.05	0.04
84	10/28/2005 12:14	2.5	WALL	BEIGE	Wall 2	CINDERBLOCK	Staircase	15	Staircase A	Negative	2.98	0.07	0.11
85	10/28/2005 12:14	2.5	WALL	BEIGE	Wall 3	CINDERBLOCK	Staircase	15	Staircase A	Negative	3.96	0.13	0.17
86	10/28/2005 12:15	5.02	LANDING	BEIGE	FLOOR	CONCRETE	Staircase	15	Staircase A	Negative	3.47	0.22	0.1

Fiterman Hall
Airtek Project #05-0867

No	Time	Dur	COMPONENT	COLOR	SIDE	SUBSTRATE	SPACE	FL #	ROOM	Results	DI	PbC	PbC Error
87	10/28/2005 12:28	20.7	Calibrate							Positive	1.09	1.2	0.1
88	10/28/2005 12:29	21.35	Calibrate							Positive	2.81	1.3	0.1
89	10/28/2005 12:32	21.34	Calibrate							Positive	1.08	1.1	0.1
90	10/28/2005 12:32	21.35	Calibrate							Positive	2.78	1.2	0.1
91	10/31/2005 9:05	56.68	SHUTTER_CAL									8.29	0
92	10/31/2005 9:14	21.86	Calibrate							Positive	1.04	1	0.1
93	10/31/2005 9:15	21.23	Calibrate							Positive	2.72	1.2	0.1
94	10/31/2005 9:23	1.88	Stair Riser	RED	Room Center	METAL	Staircase	1	Staircase CTR.	Negative	1	0	0.02
95	10/31/2005 9:24	3.76	Stair Tread	RED	Room Center	METAL	Staircase	1	Staircase CTR.	Negative	2.29	0.01	0.03
96	10/31/2005 9:25	2.49	Hand Rail	RED	Room Center	METAL	Staircase	1	Staircase CTR.	Negative	1	0	0.02
97	10/31/2005 9:25	2.49	Stair Strin	RED	Room Center	METAL	Staircase	1	Staircase CTR.	Negative	1	0	0.02
98	10/31/2005 9:27	1.89	Stair Riser	RED	Room Center	METAL	Staircase	3	Staircase CTR.	Negative	1	0	0.02
99	10/31/2005 9:28	4.37	Stair Tread	RED	Room Center	METAL	Staircase	3	Staircase CTR.	Negative	1.89	0	0.02
100	10/31/2005 9:28	1.87	Hand Rail	RED	Room Center	METAL	Staircase	3	Staircase CTR.	Negative	1	0	0.02
101	10/31/2005 9:30	1.87	Stair Strin	RED	Room Center	METAL	Staircase	3	Staircase CTR.	Negative	1	0	0.02
102	10/31/2005 9:33	1.87	Staircase Db	GRAY	Side 1	METAL	Staircase	1	Staircase B	Negative	3.48	0.07	0.13
103	10/31/2005 9:34	1.88	Staircase Dr.	BEIGE	Side 1	METAL	Staircase	1	Staircase B	Negative	4.1	0.05	0.12
104	10/31/2005 9:36	4.37	Wall	BEIGE	Wall 1	CONCRETE	Staircase	1	Staircase B	Negative	1.4	0.02	0.02
105	10/31/2005 9:36	3.74	Wall	BEIGE	WALL 3	CONCRETE	Staircase	1	Staircase B	Negative	1.91	0.01	0.02
106	10/31/2005 9:36	4.37	Wall	BEIGE	WALL 4	CONCRETE	Staircase	1	Staircase B	Negative	2.13	0.05	0.04
107	10/31/2005 9:38	2.49	Standpipe	ORANGE	WALL 3	METAL	Staircase	1	Staircase B	Negative	2.91	0.12	0.13
108	10/31/2005 9:39	1.88	Stair Riser	BEIGE	ROOM CENTER	METAL	Staircase	1	Staircase B	Negative	3.69	0.4	0.3
109	10/31/2005 9:41	4.36	Stair Tread	BEIGE	ROOM CENTER	METAL	Staircase	1	Staircase B	Negative	2.48	0.01	0.02
110	10/31/2005 9:41	1.87	Baluster	BEIGE	ROOM CENTER	METAL	Staircase	1	Staircase B	Null	5.24	0.4	0.4
111	10/31/2005 9:42	4.36	Baluster	BEIGE	ROOM CENTER	METAL	Staircase	1	Staircase B	Negative	5.79	-0.48	1.12
112	10/31/2005 9:43	1.87	Hand Rail	BEIGE	ROOM CENTER	METAL	Staircase	1	Staircase B	Negative	4.27	0.23	0.27
113	10/31/2005 9:45	1.87	Staircase Db	LT-YELLOW	Side 1	METAL	Staircase	3	Staircase B	Negative	1	0	0.02
114	10/31/2005 9:46	1.88	Staircase Dr	LT-YELLOW	Side 1	METAL	Staircase	3	Staircase B	Negative	1	0.01	0.03
115	10/31/2005 9:47	4.37	Wall	BEIGE	Side 1	PLASTER	Staircase	3	Staircase B	Negative	1	0	0.02
116	10/31/2005 9:47	6.23	Wall	BEIGE	Side 3	PLASTER	Staircase	3	Staircase B	Negative	1.62	0.02	0.02
117	10/31/2005 9:48	5	Wall	BEIGE	Side 4	PLASTER	Staircase	3	Staircase B	Negative	1.43	0.01	0.02
118	10/31/2005 9:49	2.49	Standpipe	ORANGE	Side 3	METAL	Staircase	3	Staircase B	Negative	2.29	0.06	0.08
119	10/31/2005 9:50	1.87	Stair Riser	BEIGE	Room Center	METAL	Staircase	3	Staircase B	Negative	1.78	0.12	0.12
120	10/31/2005 9:50	4.36	Stair Tread	BEIGE	Room Center	METAL	Staircase	3	Staircase B	Negative	2.61	0.25	0.09
121	10/31/2005 9:52	1.87	Hand Rail	BEIGE	Room Center	METAL	Staircase	3	Staircase B	Negative	1	0	0.02
122	10/31/2005 9:52	2.49	Stair Strin	BEIGE	Room Center	METAL	Staircase	3	Staircase B	Negative	2.06	0.03	0.05
123	10/31/2005 9:53	1.25	Newel Post	BEIGE	Room Center	METAL	Staircase	3	Staircase B	Negative	4.56	0.08	0.2
124	10/31/2005 9:53	1.88	Baluster	BEIGE	Room Center	METAL	Staircase	3	Staircase B	Negative	1.63	0.09	0.1
125	10/31/2005 9:53	1.87	Stair Under	BEIGE	Room Center	METAL	Staircase	3	Staircase B	Negative	1.62	0.02	0.04
126	10/31/2005 9:56	3.12	WALL	BEIGE	WALL 1	CONCRETE	Staircase	6	Staircase B	Negative	1.95	0.01	0.03
127	10/31/2005 9:57	3.12	WALL	BEIGE	WALL 2	CONCRETE	Staircase	6	Staircase B	Negative	1.43	0.01	0.02
128	10/31/2005 9:57	4.36	WALL	BEIGE	WALL 3	CONCRETE	Staircase	6	Staircase B	Negative	5.33	0.02	0.05
129	10/31/2005 9:57	4.99	WALL	BEIGE	WALL 4	CONCRETE	Staircase	6	Staircase B	Negative	5.61	0.03	0.05

Fiterman Hall
Airtek Project #05-0867

No	Time	Dur	COMPONENT	COLOR	SIDE	SUBSTRATE	SPACE	FL #	ROOM	Results	DI	PbC	PbC Error
130	10/31/2005 9:58	2.5	Standpipe	ORANGE	WALL 4	METAL	Staircase	6	Staircase B	Negative	2.33	0.03	0.06
131	10/31/2005 10:01	2.5	Column	BEIGE	WALL 2	PLASTER	Staircase	6	Staircase B	Null	10	0.08	0.25
132	10/31/2005 10:01	1.87	VENT COVER	BEIGE	WALL 2	METAL	Staircase	6	Staircase B	Negative	1	0	0.02
133	10/31/2005 10:03	1.87	Stair Riser	BEIGE	ROOM CENTER	METAL	Staircase	6	Staircase B	Negative	1.56	0.11	0.1
134	10/31/2005 10:03	6.24	Stair Tread	BEIGE	ROOM CENTER	METAL	Staircase	6	Staircase B	Null	2.64	0.25	0.08
135	10/31/2005 10:04	3.12	Stair Strin	BEIGE	ROOM CENTER	METAL	Staircase	6	Staircase B	Negative	1.41	0.01	0.03
136	10/31/2005 10:05	1.87	Hand Rail	BEIGE	ROOM CENTER	METAL	Staircase	6	Staircase B	Negative	1	0.03	0.04
137	10/31/2005 10:05	1.87	Newel Post	BEIGE	ROOM CENTER	METAL	Staircase	6	Staircase B	Negative	1.65	0.04	0.07
138	10/31/2005 10:06	1.87	Baluster	BEIGE	ROOM CENTER	METAL	Staircase	6	Staircase B	Negative	3	0.2	0.25
139	10/31/2005 10:06	1.87	Stair Under	BEIGE	ROOM CENTER	METAL	Staircase	6	Staircase B	Negative	1	0	0.02
140	10/31/2005 10:11	3.12	WALL	PURPLE	WALL 1	PLASTER	Staircase	12	Staircase B	Negative	2	0.01	0.03
141	10/31/2005 10:11	6.23	WALL	PURPLE	WALL 2	PLASTER	Staircase	12	Staircase B	Negative	1	0	0.02
142	10/31/2005 10:12	3.74	WALL	PURPLE	WALL 3	PLASTER	Staircase	12	Staircase B	Negative	7.64	0.04	0.08
143	10/31/2005 10:12	4.36	WALL	PURPLE	WALL 4	PLASTER	Staircase	12	Staircase B	Negative	2.39	0.01	0.02
144	10/31/2005 10:13	1.88	Stair Riser	BEIGE	ROOM CENTER	METAL	Staircase	12	Staircase B	Negative	1.68	0.06	0.1
145	10/31/2005 10:14	4.37	Stair Tread	BEIGE	ROOM CENTER	METAL	Staircase	12	Staircase B	Negative	3.66	0.23	0.11
146	10/31/2005 10:15	1.88	Stair Strin	BEIGE	ROOM CENTER	METAL	Staircase	12	Staircase B	Negative	1	0.01	0.02
147	10/31/2005 10:15	1.87	Hand Rail	BEIGE	ROOM CENTER	METAL	Staircase	12	Staircase B	Negative	1.08	0.01	0.03
148	10/31/2005 10:16	1.87	NEWEL POST	BEIGE	ROOM CENTER	METAL	Staircase	12	Staircase B	Negative	2.28	0.04	0.08
149	10/31/2005 10:16	1.87	Baluster	BEIGE	ROOM CENTER	METAL	Staircase	12	Staircase B	Negative	2.29	0.12	0.13
150	10/31/2005 10:17	4.36	Stair Under	BEIGE	ROOM CENTER	METAL	Staircase	12	Staircase B	Negative	6.33	-0.5	1.09
151	10/31/2005 10:20	0.62	Roof DrBuck	YELLOW	WALL 1	METAL	Staircase	15	Staircase B	Null	1	0.01	0.05
152	10/31/2005 10:21	1.87	Roof DrBuck	YELLOW	WALL 1	METAL	Staircase	15	Staircase B	Negative	7.17	0.12	0.27
153	10/31/2005 10:21	1.87	Roof DOOR	YELLOW	WALL 1	METAL	Staircase	15	Staircase B	Negative	1	0	0.02
154	10/31/2005 10:22	1.88	STANDPIPE	ORANGE	WALL 3	METAL	Staircase	15	Staircase B	Negative	1.91	0.03	0.06
155	10/31/2005 10:24	1.89	PIPES	PURPLE	WALL 3	FIBERGLASS	Staircase	15	Staircase B	Negative	1	0	0.02
156	10/31/2005 10:25	1.87	Stair Riser	BEIGE	Room Center	METAL	Staircase	15	Staircase B	Negative	1.52	0.06	0.07
157	10/31/2005 10:25	4.99	Stair Tread	BEIGE	Room Center	METAL	Staircase	15	Staircase B	Negative	1.73	0.05	0.03
158	10/31/2005 10:25	1.87	Baluster	BEIGE	Room Center	METAL	Staircase	15	Staircase B	Negative	1.94	0.07	0.09
159	10/31/2005 10:26	1.87	Stair Strin	BEIGE	Room Center	METAL	Staircase	15	Staircase B	Negative	1	0.01	0.02
160	10/31/2005 10:27	2.49	Hand Rail	BEIGE	Room Center	METAL	Staircase	15	Staircase B	Negative	3	0.05	0.09
161	10/31/2005 10:27	1.87	Newel Post	BEIGE	Room Center	METAL	Staircase	15	Staircase B	Negative	2.32	0.05	0.08
162	10/31/2005 10:28	0.62	Column	BEIGE	Side 2	PLASTER	Staircase	15	Staircase B	Null	1	0.04	0.1
163	10/31/2005 10:28	4.99	Column	BEIGE	Side 2	PLASTER	Staircase	15	Staircase B	Negative	1.35	0.04	0.02
164	10/31/2005 10:42	3.12	WALL	BEIGE	WALL 1	SHEETROCK	Staircase	1	Staircase C	Negative	1	0	0.02
165	10/31/2005 10:43	2.49	WALL	BEIGE	WALL 3	SHEETROCK	Staircase	1	Staircase C	Negative	1	0	0.02
166	10/31/2005 10:44	2.49	WALL	BEIGE	WALL 4	SHEETROCK	Staircase	1	Staircase C	Negative	1	0	0.02
167	10/31/2005 10:45	1.87	Stair Riser	BEIGE	ROOM CENTER	METAL	Staircase	1	Staircase C	Negative	1	0	0.02
168	10/31/2005 10:48	4.36	STAIR TREAD	BEIGE	ROOM CENTER	METAL	Staircase	1	Staircase C	Negative	1	0	0.02
169	10/31/2005 10:48	1.25	Baluster	BEIGE	ROOM CENTER	METAL	Staircase	1	Staircase C	Negative	1	0	0.02
170	10/31/2005 10:49	1.88	Hand Rail	BEIGE	ROOM CENTER	METAL	Staircase	1	Staircase C	Negative	1	0	0.02
171	10/31/2005 10:52	4.99	WALL	PURPLE	Wall 1	PLASTER	Staircase	5	Staircase C	Negative	7.67	0.07	0.1
172	10/31/2005 10:52	6.86	WALL	PURPLE	Wall 2	PLASTER	Staircase	5	Staircase C	Negative	3.25	0.02	0.03

Fiterman Hall
Airtek Project #05-0867

No	Time	Dur	COMPONENT	COLOR	SIDE	SUBSTRATE	SPACE	FL #	ROOM	Results	DI	PbC	PbC Error
173	10/31/2005 10:53	0.62	WALL	PURPLE	Wall 3	PLASTER	Staircase	5	Staircase C	Null	2.83	0.04	0.21
174	10/31/2005 10:53	3.74	WALL	PURPLE	Wall 3	PLASTER	Staircase	5	Staircase C	Negative	1.45	0.01	0.02
175	10/31/2005 10:54	3.75	WALL	PURPLE	Wall 4	PLASTER	Staircase	5	Staircase C	Negative	4.04	0.04	0.06
176	10/31/2005 10:54	1.87	STANDPIPE	ORANGE	Wall 4	METAL	Staircase	5	Staircase C	Negative	2.78	0.02	0.07
177	10/31/2005 10:57	3.76	Staircase Db	TEAL	Wall 1	METAL	Staircase	5	Staircase C	Negative	3.8	0.6	0.2
178	10/31/2005 10:57	1.87	Staircase Dr	TEAL	Wall 1	METAL	Staircase	5	Staircase C	Null	5.9	0.6	0.5
179	10/31/2005 10:58	1.87	Stair Riser	BEIGE	Room Center	METAL	Staircase	5	Staircase C	Negative	2.05	0.18	0.19
180	10/31/2005 10:59	4.36	Stair Tread	BEIGE	Room Center	METAL	Staircase	5	Staircase C	Negative	5.21	0.5	0.2
181	10/31/2005 11:00	1.87	Stair Strin	BEIGE	Room Center	METAL	Staircase	5	Staircase C	Negative	1.18	0.01	0.03
182	10/31/2005 11:01	1.87	Hand Rail	BEIGE	Room Center	METAL	Staircase	5	Staircase C	Negative	1.99	0.05	0.08
183	10/31/2005 11:02	4.37	Newel Post	BEIGE	Room Center	METAL	Staircase	5	Staircase C	Negative	6.27	-0.42	1.16
184	10/31/2005 11:02	1.87	Baluster	BEIGE	Room Center	METAL	Staircase	5	Staircase C	Negative	1.48	0.1	0.09
185	10/31/2005 11:03	1.88	Stair Under	BEIGE	Room Center	METAL	Staircase	5	Staircase C	Negative	2.33	0.18	0.17
186	10/31/2005 11:07	4.38	WALL	BEIGE	WALL 1	PLASTER	Staircase	10	Staircase C	Negative	2.36	0.04	0.03
187	10/31/2005 11:07	4.37	WALL	BEIGE	WALL 2	PLASTER	Staircase	10	Staircase C	Negative	1	0.01	0.02
188	10/31/2005 11:08	4.36	WALL	BEIGE	WALL 3	PLASTER	Staircase	10	Staircase C	Negative	3.62	0.06	0.06
189	10/31/2005 11:08	4.36	WALL	BEIGE	WALL 4	PLASTER	Staircase	10	Staircase C	Negative	3.12	0.08	0.06
190	10/31/2005 11:10	4.36	Stair Riser	BEIGE	Room Center	METAL	Staircase	10	Staircase C	Negative	2.78	0.22	0.09
191	10/31/2005 11:10	4.36	Stair TREAD	BEIGE	Room Center	METAL	Staircase	10	Staircase C	Negative	3	0.24	0.1
192	10/31/2005 11:11	4.36	Stair Strin	BEIGE	Room Center	METAL	Staircase	10	Staircase C	Negative	3.54	0.3	0.13
193	10/31/2005 11:11	1.88	Hand Rail	BEIGE	Room Center	METAL	Staircase	10	Staircase C	Negative	1	0.02	0.03
194	10/31/2005 11:12	4.36	Baluster	BEIGE	Room Center	METAL	Staircase	10	Staircase C	Negative	3.74	0.3	0.13
195	10/31/2005 11:12	5.62	Newel Post	BEIGE	Room Center	METAL	Staircase	10	Staircase C	Negative	3.17	0.23	0.09
196	10/31/2005 11:13	4.36	Stair Under	BEIGE	Room Center	METAL	Staircase	10	Staircase C	Negative	4.66	0.5	0.2
197	10/31/2005 11:18	3.74	WALL	BEIGE	Wall 1	PLASTER	Staircase	15	Staircase C	Negative	4.28	0.02	0.04
198	10/31/2005 11:18	3.76	WALL	BEIGE	Wall 2	PLASTER	Staircase	15	Staircase C	Negative	4.26	0.02	0.04
199	10/31/2005 11:18	4.36	WALL	BEIGE	Wall 3	PLASTER	Staircase	15	Staircase C	Negative	1.97	0.01	0.02
200	10/31/2005 11:19	2.49	WALL	BEIGE	Wall 4	PLASTER	Staircase	15	Staircase C	Null	4.26	0.02	0.08
201	10/31/2005 11:20	1.87	ElectCondit	ORANGE	Wall 2	METAL	Staircase	15	Staircase C	Negative	1	0	0.02
202	10/31/2005 11:21	1.87	Stair Riser	BEIGE	Room Center	METAL	Staircase	15	Staircase C	Negative	5.28	0.07	0.17
203	10/31/2005 11:21	1.88	Stair Tread	BEIGE	Room Center	METAL	Staircase	15	Staircase C	Negative	4.42	0.06	0.14
204	10/31/2005 11:22	3.12	Stair Strin	BEIGE	Room Center	METAL	Staircase	15	Staircase C	Null	3.61	0.05	0.09
205	10/31/2005 11:22	3.75	Hand Rail	BEIGE	Room Center	METAL	Staircase	15	Staircase C	Negative	3.44	0.05	0.09
206	10/31/2005 11:22	1.88	Newel Post	BEIGE	Room Center	METAL	Staircase	15	Staircase C	Negative	4.36	0.09	0.17
207	10/31/2005 11:23	1.88	Baluster	BEIGE	Room Center	METAL	Staircase	15	Staircase C	Negative	3.49	0.05	0.11
208	10/31/2005 11:23	4.36	Stair Under	BEIGE	Room Center	METAL	Staircase	15	Staircase C	Negative	3.85	-0.6	1.19
209	10/31/2005 11:35	13.78	Calibrate							Positive	1.09	1.1	0.1
210	10/31/2005 11:37	10	Calibrate							Positive	1.1	1.1	0.1
211	10/31/2005 11:38	21.28	Calibrate							Positive	1.07	1.1	0.1
212	10/31/2005 11:38	21.87	Calibrate							Positive	2.78	1.2	0.1
213	11/1/2005 8:24	56.67	SHUTTER_CAL									8.12	0
214	11/1/2005 8:31	21.26	Calibrate							Positive	1.06	1.1	0.1
215	11/1/2005 8:32	21.25	Calibrate							Positive	2.77	1.2	0.1

Fiterman Hall
Airtek Project #05-0867

No	Time	Dur	COMPONENT	COLOR	SIDE	SUBSTRATE	SPACE	FL #	ROOM	Results	DI	PbC	PbC Error
216	11/1/2005 9:08	3.12	COLUMN	BROWN	ROOM CENTER	STEEL	NE CORNER	3		Negative	1	0	0.02
217	11/1/2005 9:13	1.87	COLUMN	BROWN	ROOM CENTER	STEEL	SOUTHSIDE	3		Negative	1	0	0.02
218	11/1/2005 9:18	1.89	COLUMN	RED	ROOM CENTER	PLASTER	EASTSIDE	4		Positive	1.37	2.4	0.6
219	11/1/2005 9:21	4.36	WALL	BEIGE	WALL 4	PLASTER	SOUTHSIDE	4		Negative	3.57	0.03	0.04
220	11/1/2005 9:23	1.87	COLUMN	BROWN	ROOM CENTER	STEEL	SOUTHSIDE	4		Negative	1	0	0.02
221	11/1/2005 9:25	3.12	COLUMN	BLUE	ROOM CENTER	PLASTER	WESTSIDE	5		Negative	1	0	0.02
222	11/1/2005 9:29	0.62	COLUMN	BROWN	ROOM CENTER	STEEL	NE CORNER	5	F501	Null	1	0	0.02
223	11/1/2005 9:29	1.87	COLUMN	BROWN	ROOM CENTER	PLASTER	NE CORNER	5	F501	Negative	1	0	0.02
224	11/1/2005 9:33	1.88	COLUMN	BROWN	ROOM CENTER	STEEL	EASTSIDE	5	F507	Negative	1	0	0.02
225	11/1/2005 9:34	3.76	COLUMN	WHITE	ROOM CENTER	PLASTER	EASTSIDE	5	F507	Negative	1	0	0.02
226	11/1/2005 9:36	1.88	COLUMN	BROWN	ROOM CENTER	STEEL	SE CORNER	5		Negative	1	0	0.02
227	11/1/2005 9:38	1.87	Pipe-Sewage	BROWN	ROOM CENTER	METAL	SOUTHSIDE	5	Exterior	Negative	1	0	0.02
228	11/1/2005 9:39	1.88	COLUMN	BROWN	ROOM CENTER	STEEL	SOUTHSIDE	5	Exterior	Negative	1	0	0.02
229	11/1/2005 9:45	1.88	COLUMN	BROWN	ROOM CENTER	STEEL	SE CORNER	7		Negative	1	0	0.02
230	11/1/2005 9:46	4.37	COLUMN	BEIGE	ROOM CENTER	PLASTER	SE CORNER	7		Negative	2.2	0.4	0.1
231	11/1/2005 9:47	1.88	COLUMN	LT-YELLOW	ROOM CENTER	PLASTER	SW CORNER	7		Negative	1	0	0.02
232	11/1/2005 9:49	1.87	COLUMN	BROWN	ROOM CENTER	STEEL	NW CORNER	7	F716	Negative	1	0	0.02
233	11/1/2005 9:51	1.89	Elev Door	YELLOW	ROOM CENTER	METAL	HALLWAY	7		Negative	1.45	0	0.02
234	11/1/2005 9:51	1.87	Elev DrBuck	YELLOW	ROOM CENTER	METAL	HALLWAY	7		Negative	1.73	0.01	0.03
235	11/1/2005 10:01	1.89	Column	BROWN	ROOM CENTER	STEEL	EASTSIDE	8		Negative	1	0	0.02
236	11/1/2005 10:11	1.87	Column	BROWN	ROOM CENTER	STEEL	WESTSIDE	8		Negative	1	0	0.02
237	11/1/2005 10:19	4.36	Column	BLUE	ROOM CENTER	PLASTER	NORTHSIDE	9		Negative	1	0	0.02
238	11/1/2005 10:23	1.88	Column	BROWN	ROOM CENTER	STEEL	EASTSIDE	9		Negative	1	0.02	0.04
239	11/1/2005 10:26	1.88	Column	WHITE	ROOM CENTER	PLASTER	SW CORNER	9		Negative	1	0	0.02
240	11/1/2005 10:49	1.88	Column	WHITE	ROOM CENTER	PLASTER	SW CORNER	10		Negative	1	0	0.02
241	11/1/2005 10:55	0.62	Column	BROWN	ROOM CENTER	STEEL	NE CORNER	10		Null	1	0	0.02
242	11/1/2005 10:56	1.87	Column	BROWN	ROOM CENTER	STEEL	NE CORNER	10		Negative	1	0	0.02
243	11/1/2005 10:59	3.12	Column	BLUE	ROOM CENTER	PLASTER	HALL	10		Negative	1	0	0.02
244	11/1/2005 11:11	1.87	Column	BROWN	ROOM CENTER	STEEL	NE CORNER	11	1131	Negative	1	0	0.02
245	11/1/2005 11:15	1.87	Column	BROWN	ROOM CENTER	STEEL	EASTSIDE	11	1131	Negative	1	0	0.02
246	11/1/2005 11:20	1.87	Column	WHITE	ROOM CENTER	PLASTER	SW CORNER	11		Negative	1	0	0.02
247	11/1/2005 11:23	1.88	Column	WHITE	ROOM CENTER	PLASTER	SW CORNER	12		Negative	1	0	0.02
248	11/1/2005 11:44	1.87	Column	BROWN	ROOM CENTER	STEEL	EASTSIDE	13		Negative	1	0	0.02
249	11/1/2005 11:50	1.88	Column	BROWN	ROOM CENTER	STEEL	NORTHSIDE	13		Negative	1	0	0.02
250	11/1/2005 12:12	4.36	Column	GRAY	ROOM CENTER	PLASTER	EASTSIDE	15		Negative	4.73	0.5	0.2
251	11/1/2005 12:17	1.87	Column	BROWN	ROOM CENTER	STEEL	SOUTHSIDE	15	MECH ROOM	Negative	1	0.06	0.07
252	11/1/2005 12:20	1.88	Column	BROWN	ROOM CENTER	STEEL	NORTHSIDE	15		Negative	1	0.06	0.06
253	11/1/2005 12:37	21.24	Calibrate							Positive	1.07	1.2	0.1
254	11/1/2005 12:38	21.24	Calibrate							Positive	3.02	1.3	0.1
255	11/1/2005 12:39	20.61	Calibrate							Positive	2.79	1.2	0.1
166	11/11/2005 11:02	56.75	SHUTTER_CAL									11.72	0
167	11/11/2005 11:05	20.32	Calibrate							Positive	1.07	1	0.1
168	11/11/2005 11:05	22.19	Calibrate							Positive	2.69	1.2	0.1

Fiterman Hall
Airtek Project #05-0867

No	Time	Dur	COMPONENT	COLOR	SIDE	SUBSTRATE	SPACE	FL #	ROOM	Results	DI	PbC	PbC Error
169	11/11/2005 11:43	1.85	Wall	LT-BLUE	Side 1	PLASTER	LOADING DOCK	1		Negative	1	0	0.02
170	11/11/2005 11:44	2.46	Wall	BEIGE	Side 2	PG BLOCK	LOADING DOCK	1		Negative	1	0.01	0.02
171	11/11/2005 11:44	2.46	Wall	LT-GREEN	Side 4	CINDERBLOCK	LOADING DOCK	1		Negative	1	0	0.02
172	11/11/2005 11:44	1.84	Column	LT-GREEN	Side 4	PLASTER	LOADING DOCK	1		Negative	1	0	0.02
173	11/11/2005 11:45	1.84	Door Buck	LT-GREEN	Side 4	METAL	LOADING DOCK	1		Negative	1	0	0.02
174	11/11/2005 11:46	6.14	Wall	MULTI-COLOR	Side 1	CERAMICTILE	Lobby	1		Negative	1	0.7	0.3
175	11/11/2005 11:47	4.3	Wall	MULTI-COLOR	Side 4	CERAMICTILE	Lobby	1		Negative	1	0.6	0.3
176	11/11/2005 11:48	3.08	Wall	WHITE	Side 1	PLASTER	EAST CORNER	1		Negative	1	0	0.02
177	11/11/2005 11:48	2.46	Wall	WHITE	Side 2	SHEETROCK	EAST CORNER	1		Negative	1	0	0.02
178	11/11/2005 11:48	2.46	Wall	WHITE	Side 3	SHEETROCK	EAST CORNER	1		Negative	1	0	0.02
179	11/11/2005 11:49	1.85	Column	WHITE	Room Center	PLASTER	EAST CORNER	1		Negative	1	0	0.02
180	11/11/2005 11:49	2.46	Door Buck	WHITE	Side 1	METAL	EAST CORNER	1		Null	2.45	0.03	0.06
181	11/11/2005 11:50	17.85	Door Buck	WHITE	Side 1	METAL	EAST CORNER	1		Null	6.8	0.9	0.2
182	11/11/2005 11:50	4.91	Door Buck	WHITE	Side 1	METAL	EAST CORNER	1		Negative	6.08	0.11	0.1
183	11/11/2005 11:50	2.46	Door	BEIGE	Side 1	METAL	EAST CORNER	1		Negative	1.19	0.02	0.04
184	11/11/2005 11:51	1.84	Pipe Cover	BEIGE	Side 4	FIBERGLASS	EAST CORNER	1		Negative	1	0	0.04
185	11/11/2005 11:54	2.46	StaircaseDb	LT-GREEN	Side 1	METAL	CORR.STC.A	4		Negative	1	0	0.02
186	11/11/2005 11:54	1.85	StaircaseDr	LT-GREEN	Side 1	METAL	CORR.STC.A	4		Negative	1	0	0.02
187	11/11/2005 11:55	2.46	Wall	LT-GREEN	Side 1	PLASTER	CORR.STC.A	4		Negative	1	0	0.02
188	11/11/2005 11:55	2.46	Wall	LT-GREEN	Side 3	PLASTER	CORR.STC.A	4		Negative	1	0	0.02
189	11/11/2005 11:55	1.84	Elev DrBuck	LT-GREEN	Side 3	METAL	CORR.STC.A	4		Negative	1.81	0.02	0.05
190	11/11/2005 11:56	2.46	Elev Door	LT-GREEN	Side 3	METAL	CORR.STC.A	4		Negative	1	0	0.02
191	11/11/2005 11:58	4.91	Wall	LT-GREEN	Side 3	PLASTER	CORRIDOR STC.C South	4		Negative	10	0.5	0.3
192	11/11/2005 11:58	3.07	Wall	BEIGE	Side 3	PLASTER	CORRIDOR STC.C South	4		Negative	2.75	0.01	0.05
193	11/11/2005 11:59	2.46	Wall	BEIGE	Side 3	SHEETROCK	CORRIDOR STC.C South	4		Negative	1.81	0	0.02
194	11/11/2005 12:00	3.07	Baseboard	BEIGE	Room Center	VINYL	CORRIDOR STC.C South	4		Negative	1.66	0.01	0.02
195	11/11/2005 12:01	3.07	Baseboard	GREEN	Room Center	VINYL	CORRIDOR STC.C South	4		Negative	1.69	0.1	0.08
196	11/11/2005 12:03	1.85	Wall	PURPLE	Side 1	CINDERBLOCK	SECURITY ROOM.	4	SECURITY	Negative	1.59	0.01	0.03
197	11/11/2005 12:03	1.84	Wall	PURPLE	Side 2	CINDERBLOCK	SECURITY ROOM	4	SECURITY	Negative	2	0.04	0.08
198	11/11/2005 12:03	1.84	Wall	PURPLE	Side 3	PLASTER	SECURITY ROOM.	4	SECURITY	Negative	1	0	0.02
199	11/11/2005 12:04	2.46	Wall	PURPLE	Side 3	BRICK	SECURITY ROOM	4	SECURITY	Negative	4.2	0.02	0.08
200	11/11/2005 12:04	3.08	Wall	PURPLE	Side 3	CINDERBLOCK	SECURITY ROOM	4	SECURITY	Negative	2.39	0.01	0.03
201	11/11/2005 12:04	3.07	Baseboard	GRAY	Side 2	VINYL	SECURITY ROOM	4	SECURITY	Negative	1	0	0.02
202	11/11/2005 12:07	1.84	Wall	WHITE	WEST	BRICK	SETBACK ROOF	6	Roof	Negative	1	0.01	0.03
203	11/11/2005 12:08	1.84	Wall	WHITE	NORTH	BRICK	SETBACK ROOF	6	Roof	Negative	1	0	0.02
204	11/11/2005 12:08	1.85	Fence-Bar	BLACK	NORTH	METAL	SETBACK ROOF	6	Roof	Negative	1.77	0.05	0.19
205	11/11/2005 12:10	1.85	RadiatorCov	GRAY	WEST	METAL	Office	6	Office	Negative	1	0	0.02
206	11/11/2005 12:10	1.84	Wall	BEIGE	WEST	SHEETROCK	Office	6	Office	Negative	1	0	0.02
207	11/11/2005 12:13	1.84	Wall	BEIGE	Side 1	CERAMICTILE	LADIES RM BY STC. A	6	Ladies Room	Negative	1.93	0.03	0.1
208	11/11/2005 12:13	2.46	Wall	BEIGE	Side 2	CERAMICTILE	LADIES RM BY STC. A	6	Ladies Room	Negative	3.59	0.07	0.2
209	11/11/2005 12:13	1.85	Wall	BEIGE	Side 4	CERAMICTILE	LADIES RM BY STC. A	6	Ladies Room	Negative	1.59	0.02	0.07
210	11/11/2005 12:14	1.84	Floor	GRAY	Floor	CERAMICTILE	LADIES RM BY STC. A	6	Ladies Room	Negative	1	0	0.02
211	11/11/2005 12:14	1.85	Toilet	WHITE	Side 2	CERAMIC	LADIES RM BY STC. A	6	Ladies Room	Negative	7.73	0.16	0.41

Fiterman Hall
Airtek Project #05-0867

No	Time	Dur	COMPONENT	COLOR	SIDE	SUBSTRATE	SPACE	FL #	ROOM	Results	DI	PbC	PbC Error
212	11/11/2005 12:15	2.46	Stall Door	LT-GREEN	Side 2	METAL	LADIES RM BY STC. A	6	Ladies Room	Negative	1	0	0.02
213	11/11/2005 12:15	2.46	Sink	WHITE	Side 3	CERAMIC	LADIES RM BY STC. A	6	Ladies Room	Negative	2.19	0.04	0.08
214	11/11/2005 12:18	1.85	SecureGate	BEIGE	Side 2	METAL	StorageArea	8	SUPPLY	Negative	1	0	0.02
215	11/11/2005 12:18	1.84	Wall	BEIGE	Side 2	SHEETROCK	StorageArea	8	SUPPLY	Negative	1.18	0	0.02
216	11/11/2005 12:19	1.85	Wall	BEIGE	Side 3	SHEETROCK	StorageArea	8	SUPPLY	Negative	1.23	0	0.02
217	11/11/2005 12:19	2.47	Door Buck	BEIGE	Side 3 WEST	METAL	StorageArea	8	SUPPLY	Negative	1	0	0.02
218	11/11/2005 12:19	1.85	Door	BEIGE	Side 3 WEST	METAL	StorageArea	8	SUPPLY	Negative	1	0	0.02
219	11/11/2005 12:21	2.46	Wall	BEIGE	RC S.W.CORNER	PLASTER	Exterior	8	Exterior	Negative	1	0.01	0.02
220	11/11/2005 12:22	0.61	Column	BEIGE	RC S.W.CORNER	PLASTER	Exterior	8	Exterior	Null	2.47	0.08	0.27
221	11/11/2005 12:22	1.23	Column	BEIGE	RC S.W.CORNER	PLASTER	Exterior	8	Exterior	Null	1.46	0.04	0.08
222	11/11/2005 12:22	1.84	Column	BEIGE	RC S.W.CORNER	PLASTER	Exterior	8	Exterior	Negative	4.13	0.13	0.2
223	11/11/2005 12:22	2.46	Column	GRAY	RC S.W.CORNER	STEEL	Exterior	8	Exterior	Negative	1	0	0.02
224	11/11/2005 12:25	1.84	Wall	LT-BLUE	Side 1	PLASTER	ELEC. RM BY STC. A	9	ELEC. RM	Negative	1	0	0.02
225	11/11/2005 12:25	3.07	Wall	LT-BLUE	Side 2	PLASTER	ELEC. RM BY STC. A	9	ELEC. RM	Negative	1	0	0.02
226	11/11/2005 12:25	1.84	Wall	LT-BLUE	Side 3	PLASTER	ELEC. RM BY STC. A	9	ELEC. RM	Negative	1	0	0.02
227	11/11/2005 12:25	1.23	Wall	LT-BLUE	Side 4	PLASTER	ELEC. RM BY STC. A	9	ELEC. RM	Negative	1	0	0.02
228	11/11/2005 12:26	1.85	Door Buck	LT-GREEN	Side 1	METAL	ELEC. RM BY STC. A	9	ELEC. RM	Negative	1	0	0.02
229	11/11/2005 12:26	3.07	Baseboard	GRAY	Side 1	VINYL	ELEC. RM BY STC. A	9	ELEC. RM	Negative	1	0	0.02
230	11/11/2005 12:27	2.46	Column	BLUE	RC EAST	PLASTER	Office	9	OFFICE	Negative	1	0	0.02
231	11/11/2005 12:28	3.07	Column	BLUE	RC EAST	PLASTER	Office	9	OFFICE	Negative	2.99	0.01	0.04
232	11/11/2005 12:28	2.47	Wall	BEIGE	RC EAST	PLASTER	Office	9	OFFICE	Negative	1	0	0.02
233	11/11/2005 12:28	3.07	Wall	LT-GREEN	RC EAST	PLASTER	Office	9	OFFICE	Negative	1	0	0.02
234	11/11/2005 12:29	2.46	Baseboard	LT-GREEN	RC EAST	VINYL	Office	9	OFFICE	Negative	2.84	0.26	0.2
235	11/11/2005 12:29	6.76	Baseboard	BLACK	RC EAST	VINYL	Office	9	OFFICE	Negative	1.79	0.06	0.03
236	11/11/2005 12:31	1.84	Door Buck	BEIGE	WEST WALL 1	METAL	Office	9	OFFICE	Negative	1	0	0.02
237	11/11/2005 12:31	1.86	Door	BEIGE	WEST WALL 1	METAL	Office	9	OFFICE	Negative	1	0	0.02
238	11/11/2005 12:31	2.46	Wall	BEIGE	WEST WALL 1	PLASTER	Office	9	OFFICE	Negative	1	0	0.02
239	11/11/2005 12:32	1.84	Wall	BEIGE	WEST Wall 2	PLASTER	Office	9	OFFICE	Negative	1	0	0.02
240	11/11/2005 12:32	2.46	Wall	BEIGE	WEST WALL 3	PLASTER	Office	9	OFFICE	Negative	1	0	0.02
241	11/11/2005 12:32	2.46	Wall	BEIGE	4	PLASTER	Office	9	OFFICE	Negative	1.77	0	0.02
242	11/11/2005 12:33	2.46	Column	BEIGE	SOUTH	STEEL	Office	9	OFFICE	Negative	1	0	0.02
243	11/11/2005 12:34	1.84	Pipe Riser	BEIGE	SOUTH	STEEL	Office	9	OFFICE	Negative	1	0	0.02
244	11/11/2005 12:34	1.86	Pipe RisRt	BEIGE	SOUTH	STEEL	Office	9	OFFICE	Negative	2.94	0.08	0.22
245	11/11/2005 12:34	1.85	Pipe-Sewage	BEIGE	SOUTH	STEEL	Office	9	OFFICE	Negative	1	0	0.02
246	11/11/2005 12:35	1.84	ElectCondit	BEIGE	SOUTH	STEEL	Office	9	OFFICE	Negative	1	0	0.02
247	11/11/2005 12:39	1.84	Wall	LT-GREEN	SOUTH	CINDERBLOCK	OPEN OFFICE AREA	11	OPEN AREA	Negative	1	0	0.02
248	11/11/2005 12:39	1.85	Wall	LT-GREEN	SOUTH	PLASTER	OPEN OFFICE AREA	11	OPEN AREA	Negative	1.22	0	0.02
249	11/11/2005 12:40	1.84	Door Buck	LT-GREEN	SOUTH	METAL	OPEN OFFICE AREA	11	OPEN AREA	Negative	2.93	0.09	0.13
250	11/11/2005 12:40	2.47	Floor	GRAY	Floor	CONCRETE	OPEN OFFICE AREA	11	OPEN AREA	Negative	1.51	0.12	0.09
251	11/11/2005 12:41	1.85	Pipe	LT-GREEN	SOUTH	METAL	OPEN OFFICE AREA	11	OPEN AREA	Negative	1	0.01	0.03
252	11/11/2005 12:41	2.46	Column	LT-GREEN	SOUTH	PLASTER	OPEN OFFICE AREA	11	OPEN AREA	Negative	1	0	0.02
253	11/11/2005 12:41	1.85	Column	LT-GREEN	SOUTH	STEEL	OPEN OFFICE AREA	11	OPEN AREA	Negative	1	0	0.02
254	11/11/2005 12:42	2.46	Pipe-Sewage	LT-GREEN	SOUTH	METAL	OPEN OFFICE AREA	11	OPEN AREA	Negative	1	0	0.02

Fiterman Hall
Airtek Project #05-0867

No	Time	Dur	COMPONENT	COLOR	SIDE	SUBSTRATE	SPACE	FL #	ROOM	Results	DI	PbC	PbC Error
255	11/11/2005 12:42	1.84	Pipe Riser	LT-GREEN	SOUTH	METAL	OPEN OFFICE AREA	11	OPEN AREA	Negative	1	0	0.02
256	11/11/2005 12:42	1.84	Pipe RiserRt	LT-GREEN	SOUTH	METAL	OPEN OFFICE AREA	11	OPEN AREA	Negative	1	0	0.02
257	11/11/2005 12:43	2.46	Wall	LT-GREEN	SOUTH	BRICK	OPEN OFFICE AREA	11	OPEN AREA	Negative	1.06	0	0.02
258	11/11/2005 12:45	3.07	Wall	LT-GREEN	NORTH	PLASTER	LUNCH ROOM	11	LUNCHEON	Negative	1	0	0.02
259	11/11/2005 12:45	1.84	Wall	LT-GREEN	NORTH WALL 2	PLASTER	LUNCH ROOM	11	LUNCHEON	Negative	1	0	0.02
260	11/11/2005 12:45	2.46	Wall	LT-GREEN	NORTH WALL 3	PLASTER	LUNCH ROOM	11	LUNCHEON	Negative	2.09	0.4	0.5
261	11/11/2005 12:46	1.84	Pipe Cover	LT-GREEN	NORTH WALL 3	FIBERGLASS	LUNCH ROOM	11	LUNCHEON	Negative	1	0.13	0.35
262	11/11/2005 12:47	2.47	Column	LT-GREEN	NORTH WALL 3	PLASTER	LUNCH ROOM	11	LUNCHEON	Negative	1.1	0	0.02
263	11/11/2005 12:53	2.46	Stair Riser	BEIGE	Room Center	METAL	Staircase	B	Basement	Negative	1	0	0.02
264	11/11/2005 12:53	1.84	Hand Rail	BEIGE	Room Center	METAL	Staircase	B	Basement	Negative	1	0	0.02
265	11/11/2005 12:53	3.07	Floor	BEIGE	Floor	CONCRETE	Staircase	B	Basement	Negative	1	0	0.02
266	11/11/2005 12:54	2.46	Door Buck	BEIGE	Side 1	METAL	Staircase	B	Basement	Negative	1	0	0.02
267	11/11/2005 12:54	1.85	Door	BEIGE	Side 1	METAL	Staircase	B	Basement	Negative	1	0	0.02
268	11/11/2005 12:54	1.84	Wall	BEIGE	Side 1	PLASTER	Staircase	B	Basement	Negative	1	0	0.02
269	11/11/2005 12:54	1.85	Wall	BEIGE	Side 4	PLASTER	Staircase	B	Basement	Negative	1	0	0.02
270	11/11/2005 12:55	3.07	Wall	BEIGE	Side 4	CINDERBLOCK	Staircase	B	Basement	Negative	2.82	0.01	0.04
271	11/11/2005 12:56	1.84	Wall	LT-GREEN	Side 1	CINDERBLOCK	MER	B	Basement	Negative	1	0	0.02
272	11/11/2005 12:56	1.84	Wall	LT-GREEN	Side 4	CINDERBLOCK	MER	B	Basement	Negative	1	0	0.02
273	11/11/2005 12:57	22.73	Sink	WHITE	Room Center	CERAMIC	MER	B	Basement	Null	2.44	0.18	0.03
274	11/11/2005 12:58	1.84	Sink	WHITE	Room Center	CERAMIC	MER	B	Basement	Positive	2.14	2.8	0.8
275	11/11/2005 12:58	2.46	Pipe-Sewage	WHITE	Room Center	CERAMIC	MER	B	Basement	Negative	1.96	0.23	0.18
276	11/11/2005 12:58	2.46	Pipe	LT-GREEN	Room Center	METAL	MER	B	Basement	Negative	1.53	0.12	0.1
277	11/11/2005 12:59	4.95	Column	LT-GREEN	Room Center	CINDERBLOCK	MER	B	Basement	Negative	3.48	0.25	0.1
278	11/11/2005 13:00	2.46	Door Buck	WHITE	Room Center	WOOD	Office	B	Basement	Negative	1	0	0.02
279	11/11/2005 13:00	1.84	Door	WHITE	Room Center	WOOD	Office	B	Basement	Negative	1	0	0.02
280	11/11/2005 13:01	1.84	Wall	WHITE	Room Center	SHEETROCK	Office	B	Basement	Negative	1	0	0.02
281	11/11/2005 13:01	2.46	Wall	WHITE	Side 4	SHEETROCK	Office	B	Basement	Negative	1	0	0.02
282	11/11/2005 13:02	1.85	Column	WHITE	Room Center	PLASTER	Office	B	Basement	Negative	2.65	0.02	0.07
283	11/11/2005 13:02	1.84	Floor	GRAY	Floor	CONCRETE	Office	B	Basement	Negative	1.82	0.13	0.13
284	11/11/2005 13:10	11.68	Calibrate							Positive	1.08	1.1	0.1
285	11/11/2005 13:10	21.54	Calibrate							Positive	2.67	1.1	0.1