

Fiterman Hall Exterior Lead-Based Paint Testing Results

No	Time	COMPONENT	COLOR	SIDE	SUBSTRATE	SPACE	FL #	ROOM	Results	DI	PbC	PbC Error
202	11/11/2005 12:07	Wall	WHITE	WEST	BRICK	SETBACK ROOF	6	Roof	Negative	1	0.01	0.03
203	11/11/2005 12:08	Wall	WHITE	NORTH	BRICK	SETBACK ROOF	6	Roof	Negative	1	0	0.02
219	11/11/2005 12:21	Wall	BEIGE	RC S.W.CORNER	PLASTER	Exterior	8	Exterior	Negative	1	0.01	0.02
220	11/11/2005 12:22	Column	BEIGE	RC S.W.CORNER	PLASTER	Exterior	8	Exterior	Null	2.47	0.08	0.27
221	11/11/2005 12:22	Column	BEIGE	RC S.W.CORNER	PLASTER	Exterior	8	Exterior	Null	1.46	0.04	0.08
222	11/11/2005 12:22	Column	BEIGE	RC S.W.CORNER	PLASTER	Exterior	8	Exterior	Negative	4.13	0.13	0.2
223	11/11/2005 12:22	Column	GRAY	RC S.W.CORNER	STEEL	Exterior	8	Exterior	Negative	1	0	0.02